


PRODUCT ALERT

Date	October 16, 2023
Affected Parts	Carter Mechanical Fuel Pump M6737
Fitment	 <p>1972-1973 Jeep DJ5 (Liter: 3.8 & Engine(ci): 232 & Cylinder: 6 & Block: L); 1972-1983 Jeep CJ5 (Liter: 3.8, 4.2 & Engine(ci): 232, 258 & Cylinder: 6 & Block: L); 1972-1975 Jeep CJ6 (Liter: 3.8, 4.2 & Engine(ci): 232, 258 & Cylinder: 6 & Block: L); 1976-1986 Jeep CJ7 (Liter: 4.2, 3.8, 2.5 & Engine(ci): 258, 232, 150 & Cylinder: 6, 4 & Block: L); 1974-1987 Jeep Cherokee (Liter: 4.2, 2.5 & Engine(ci): 258, 150 & Cylinder: 6, 4 & Block: L); 1986-1987 Jeep Comanche (Liter: 2.5 & Cylinder: 4 & Block: L); 1984-1986 Jeep Grand Wagoneer (Liter: 4.2 & Engine(ci): 258 & Cylinder: 6 & Block: L); 1974-1980 Jeep J10 (Liter: 4.2 & Engine(ci): 258 & Cylinder: 6 & Block: L); 1981-1985 Jeep Scrambler (Liter: 4.2, 2.5 & Engine(ci): 258, 150 & Cylinder: 6, 4 & Block: L); 1972-1987 Jeep Wagoneer (Liter: 4.2, 2.5 & Engine(ci): 258, 150 & Cylinder: 6, 4 & Block: L); 1987-1990 Jeep Wrangler (Liter: 4.2, 2.5 & Cylinder: 6, 4 & Block: L); 1970-1971 American Motors Ambassador (Liter: 3.8, 4.2 & Engine(ci): 232, 258 & Cylinder: 6 & Block: L); 1979-1983 American Motors Spirit (Liter: 4.2, 3.8 & Engine(ci): 258, 232 & Cylinder: 6 & Block: L); 1978-1980 American Motors AMX (Liter: 4.2 & Engine(ci): 258 & Cylinder: 6 & Block: L); 1978-1983 American Motors Concord (Liter: 4.2, 3.8 & Engine(ci): 258, 232 & Cylinder: 6 & Block: L); 1980-1988 American Motors Eagle (Liter: 4.2 & Engine(ci): 258 & Cylinder: 6 & Block: L); 1970-1978 American Motors Gremlin (Liter: 3.3, 3.8, 4.2 & Engine(ci): 199, 232, 258 & Cylinder: 6 & Block: L); 1970-1977 American Motors Hornet (Liter: 3.3, 3.8, 4.2 & Engine(ci): 199, 232, 258 & Cylinder: 6 & Block: L); 1971-1978 American Motors Matador (Liter: 3.8, 4.2 & Engine(ci): 232, 258 & Cylinder: 6 & Block: L); 1975-1980 American Motors Pacer (Liter: 4.2, 3.8 & Engine(ci): 258, 232 & Cylinder: 6 & Block: L)</p>

Product Issue:

- The Carter technical team reports a higher-than-normal level of product complaints/warranty requests on the Carter M6737 fuel pump.
- **We are withdrawing this part from the market while we review these problems and potential solutions.**
- We are cancelling any customer open orders and removing the part from electronic cataloging until further notice. We apologize for this inconvenience.
- If you have additional questions, please contact our Technical Support Group at technicalhotline@firstbrandsgroup.com